

Pipeline Inspection Report

Asset Information

Upstream MH: CO 1A
Rim to Invert:
Rim to Grade:
Downstream MH: 01
Rim to Invert:
Rim to Grade:
PSR:
Pipe Size: 8 in. | Circular
Material: Polyvinyl Chloride
Street: 94582 OR-99E
City: JUNCTION CITY
System Owner: DICKERHOOF PROPERTIES
Drainage Area:
Sewer Use: Sanitary
Lining Method:
Length: (unspecified)
Year Built:
Location Code:


Project Information

Project: JUNCTION CITY COMMERCIAL
Work Order:
Survey Customer: WAY TO GO CONST.
PO Number:
Additional Info: 1INCH GRADE BALL & 8" MANDRELL

Inspection Information

Date: 20220107 09:58
Surveyed By: JOSE BARRON
Certificate #: 125000000-00001
Camera Direction: Upstream
Purpose: Pre-Acceptance
Pre-Cleaning: Jetting
Date Cleaned: 20220107
Flow Control:
Length Surveyed:
Weather: Dry
Location Details:


Sketch



Schematic Top View

CO 1A

Feet	Code	Clock	Length	Value	Description	Comment
------	------	-------	--------	-------	-------------	---------



01

Snapshots




Access Point - Manhole at 000.0 feet | STARTING INSPECTION AT MH 01 GOING UPSTREAM TO CLEAN OUT



AutoSave: MWL@000.0ft (2).jpg



Water Level at 000.0 feet, 0%



Access Point - Cleanout: Mainline at 052.1 feet | END OF INSPECTION