

Pipeline Inspection Report

Asset Information

Upstream MH: 01

Rim to Invert:

Rim to Grade:

Downstream MH: 02

Rim to Invert:

Rim to Grade:

PSR:

Pipe Size: 8 in. | Circular

Material: Polyvinyl Chloride

Street: 94582 OR-99E

City: JUNCTION CITY

System Owner: DICKERHOOF PROPERTIES

Drainage Area:

Sewer Use: Sanitary

Lining Method:

Length: (unspecified)

Year Built:

Location Code:

Project Information

Project: JUNCTION CITY COMMERCIAL

Work Order:

Survey Customer: WAY TO GO CONST.

PO Number:

Additional Info: 1INCH GRADE BALL & 8" MANDRELL

Inspection Information

Date: 20220107 13:52

Surveyed By: JOSE BARRON

Certificate #: 125000000-00001

Camera Direction: Downstream

Purpose: Pre-Acceptance

Pre-Cleaning: Jetting

Date Cleaned: 20220107


Flow Control:

Length Surveyed:


Weather: Dry

Location Details:


Sketch




Schematic Top View




Snapshots




Water Level at 000.0 feet, 0%



Tap, Factory Made at 011.6 feet, 2 o'clock, 4 in



Tap, Factory Made at 019.8 feet, 2 o'clock, 4 in



Tap, Factory Made at 045.8 feet, 2 o'clock, 4 in



Tap, Factory Made: Capped at 082.0 feet, 9 o'clock, 6 in | 8 TO 6 REDUCER



General Observation at 115.0 feet | EXSISTING PIPE



Access Point - Manhole at 299.0 feet | END OF INSPECTION